



Certificate No. : T-0071

ELECTRICAL RESEARCH AND DEVELOPMENT ASSOCIATION

(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India)

ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.




EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

Fax : +91 (0265) 2638382 Web : www.erd.a.org

E-mail : erda@erd.a.org, dir@erd.a.org

**TEST REPORT**

SHEET 1 of 4

NAME & ADDRESS OF CUSTOMER. AB Power System Solution Sr. No. 16/6, Sinhagad Road, Opp. Savali Dhaba, Nanded Phata, Tal: Havali, Pune – 411 041	REPORT NO. : HCCT/06/228 DATED: 02.06.2009	
	CUSTOMER REF. NO.: Nil DATE: 17.04.2009	
	DATE OF SAMPLE RECEIPT	DATE OF TESTING
	22.04.2009(Sample) 07.05.2009(Letter)	25.05.2009 to 01.06.2009
SAMPLE DESCRIPTION LT SHUNT POWER CAPACITOR 25 kVAR, 440 V, 40/50°C PP/ SH, Δ, 50Hz. Insulation Level: 3/- kV ac Discharge Device: Resistor	SAMPLE IDENTIFICATION ERDA ID No.: HCCT-187 BRAND NAME: "AB-LIFASA" Sr. No.: IDE043179 Ref : FME	
TEST DETAILS		TEST SPECIFICATION
Type Tests		As per IS: 13340-1993 & IS: 13341-1992
TEST RESULTS : As per sheet 1 to 4.		
1. VISUAL EXAMINATION – Rating plate details. (Cl. No. 13.)		
Ref.: ISS : IEC 831 Rated Out put : 25 kVAR Rated Voltage : 440 Volts Rated frequency : 50 Hz No. of phases : 3 Connection Symbol : Δ Discharge device : Resistor Manufactured By : AB Power System Solution, Pune-41.	Manufacturer's Sr. No. : IDE043179 Temperature category : 40/50°C Insulation level : 3/- kV Ref. To Self healing : SH Overpressure disconnecter : --- Type of dielectric : PP Internal fuse : Provided	
WARNING INSTRUCTION: "Discharge capacitor before handling" marked in RED colour.		
REMARKS : The sample CONFORMS EXCEPT TEST FOR DISCHARGE DEVICE to the requirements of the above mentioned ISS in the above mentioned tests.		
 PREPARED BY	 CHECKED BY	 APPROVED BY
Note : 1. This report relates only to the particular sample received for testing in good at E.R.D.A. 2. This report cannot be reproduced in part under any circumstances. 3. Publication of this report requires prior permission in writing from Director, E.R.D.A. 4. Only the tests asked for by the customer have been carried out.		

0131889

